

MXsI Release history

Version	Date	Change/additions
02.42.28	Mar, 20th 2025	<ul style="list-style-type: none">▪ ACC3 support External modules <ul style="list-style-type: none">▪ 02.42.27 ACC2▪ 02.42.27 ACC3
02.42.17	Oct, 10th 2024	<ul style="list-style-type: none">▪ K6/K8/K15 Keypad support External modules <p>No changes</p>
02.42.06	Jun, 17th 2024	<ul style="list-style-type: none">▪ LCU1S support External modules <p>No changes</p>
02.42.01	Apr, 18th 2024	<ul style="list-style-type: none">▪ ACC2 and ACC2 Open support External modules <ul style="list-style-type: none">▪ 02.40.73 ACC▪ 02.40.95 ACC2▪ 02.40.95 GPS09c/GPS09c Open/GPS09c Pro Open▪ 02.40.85 GPS09▪ 02.40.72 GPS09B▪ 1.32.30 GS-Dash
02.40.77	Oct, 11th 2023	<ul style="list-style-type: none">▪ Improved AiM CAN NET External modules <ul style="list-style-type: none">▪ 25.49 LCU-One CAN (improved warm up handling)▪ 01.32.28 MMOD Strada Logger (fix Net table in download data)▪ 02.40.73 ACC (fix sample time bug caused no recorded data)
02.40.53	Feb, 7th 2023	<ul style="list-style-type: none">▪ GPS09C support External modules <p>No changes</p>

MXsI Release history

Version	Date	Change/additions
02.40.40	Nov, 23rd 2022	<ul style="list-style-type: none">▪ Added predictive reference lap management External modules No changes
02.40.21	Jul, 27th 2022	<ul style="list-style-type: none">▪ New expansion boards (GSDASH2, RIO2_B, Shiftlight_B) support External modules <ul style="list-style-type: none">▪ 02.40.02 RIO2 Module B▪ 02.40.10 Shiftlight Module B▪ 02.40.21 GSDASH2▪ 01.32.16 GSDASH
02.40.00	May, 17th 2022	<ul style="list-style-type: none">▪ SmartyCam 3 Sport support External modules No changes
02.36.76	Sep, 10th 2021	<ul style="list-style-type: none">▪ Fixed digital speed parameters from RS3 configuration setup External modules <ul style="list-style-type: none">▪ 02.36.64 GPS09: Improved GPS data synchronization
02.34.29	Nov, 25th 2020	<ul style="list-style-type: none">▪ Added GPS09 support External modules <ul style="list-style-type: none">▪ 35.65 GPS Module: Fix Masterclock received from master that caused bad values in GPS data timestamp
02.32.78	Jul, 10th 2020	<ul style="list-style-type: none">▪ Fixed RPM issue due to wrong RPM factor handling External modules No changes

MXsI Release history

Version	Date	Change/additions
02.32.73	Jun, 9th 2020	<ul style="list-style-type: none">▪ Race Simulators handling▪ Added Hour/Date info from GPS tracks▪ Added reference speed used to calculate odometers▪ Fixed temperature and pressure channels visualization <p>External modules No changes</p>
02.32.68	Apr, 30th 2020	<ul style="list-style-type: none">▪ Time visualization together with LOG message in status bar while the system is logging▪ Odometer unit of measure fixed in menu▪ Pressure channels unit of measure fixed <p>External modules No changes</p>
02.32.55	Apr, 23rd 2020	<ul style="list-style-type: none">▪ General speed up in transmitting configuration▪ Solved missing timeout on ECU channels for some serial protocol (RS232 and K-line) (AB#59)▪ Improved track visualization▪ Digital channels: bug fix on RPM input capture▪ Fixed alarms based on BestDiff time <p>External modules No changes</p>